




KINZE and John Deere Planters



- | | | |
|---|--------|---|
| 1 | GA2327 | Lid with Clip |
| 2 | GD1053 | Seed Hopper |
| 3 | GA2027 | Retainer |
| 4 | GA2058 | Complete seed hopper with mounting brackets |




- | | | |
|---|----------|----------------------|
| 1 | GR1066 | Hopper Support |
| 2 | GD1035 | Release Handle |
| 3 | G3303-98 | Roller Chain |
| 4 | GA2007 | Hopper Latch |
| 5 | GA4822 | Meter Drive Assembly |
| 6 | GB0243 | Drive Computer |
| 7 | GD10464 | Spring |
| 8 | GD1036 | Lever |



- | | | |
|---|---------|---------------------|
| 1 | GD1041 | Belt Drive Sprocket |
| 2 | GD11286 | Seed Belter |
| 3 | GR1569 | Carrier w/ Belt |
| 4 | GA2020 | Brush |
| 5 | GD1046 | Seed Baffle |
| 6 | GR1848 | Finger Assembly |

700-01000 Corn Meter Complete



- | | | |
|---|--------|---------------------|
| 1 | GD8778 | Wear Strip |
| 2 | GA5699 | Upper Retain. Brush |
| 3 | GA5834 | Lower Brush |
| 4 | GA5794 | Seed Disc Soybean |
| 5 | G10531 | Locking Wing Nut |

700-01079 Brush Meter Complete



Service Notes

- Binkley & Hurst can calibrate your finger pick up corn meters on our Kinze T-3000 test stand.